




FLEXIBLE FILLING BOARDS

FFK 042071
FFK 056111
FFK 100112
FFK 196094



TECHNICAL PARAMETERS

model	FFK 042071	FFK 056111	FFK 100112	FFK 196094
dimensions of the plate	420 x 70 mm	560 x 115 mm	1000 x 115 mm	1960 x 90 mm
min. convex radius	350 mm	500 mm	1100 mm	2100 mm
min. concave radius	350 mm	600 mm	1000 mm	2000 mm
weight	0.8 Kg	1.1 Kg	2.3 Kg	4.5 Kg
hardness of the plate	1 (extra soft)	1 (extra soft)	2 (soft)	4 (extra hard)

USAGE

The device is intended for wiping and spreading liquid materials on convex and / or concave surfaces and for visual quality control of these areas.

PACKAGING

Carton

MANUFACTURER

INNOVIA, s.r.o.
Sterboholska 1421/37
102 00 Prague, Czech Republic

Tel: **+420 725 929 393**
info@flexisander.com
www.flexisander.com

FLEXISANDER
ahead of the curve

The manufacturer reserves the right to make changes to products.
Current information is available at www.flexisander.com. Made in Czech Republic (EU).

X FFK 056111



X FFK 100112



X FFK 196094





OWNER'S MANUAL



FFK 042071
FFK 056111
FFK 100112
FFK 196094

CAUTION!

Before operating the device, carefully read this manual and strictly follow the instructions listed below:

- ◆ The exhaust fumes of used putty are harmful to your health, therefore, always use a respiratory protection mask.
- ◆ Wear sight and hand protection.
- ◆ Follow all manufacturer's instructions of used putty.

WORK AREA SAFETY

- ◆ Use filling materials recommended for material of the surfaces.
- Keep work area clean and well lit. Cluttered or dark areas invite accidents.
- ◆ Keep children and bystanders away while operating a power tool. Distractions can cause you to lose control.
- Do not overreach. Keep proper footing and balance at all times. This enables better control of the tool in unexpected situations.
- Dress properly. Do not wear loose clothing or jewellery. Keep your hair, clothing and gloves away from moving parts. Loose clothes, jewellery or long hair can be caught in moving parts.
- Provide for good ventilation of the working place.
- It is recommended to wear a dust respirator. Observe the relevant regulations in your country for the materials to be worked.
- ◆ Prevent dust accumulation at the workplace.
- After working with putty clean tools and wash your hands with warm water.

RECYCLING

Equipment and its accessories and packaging surrender after the end of its useful life to a collection point for re-processing.



WARRANTY

We provide guarantee on material and manufacturing defects hidden under the legal provisions of the given country, at the minimum at least 12 months. In the EU, the warranty period is 24 months for exclusively private use (please see invoice or delivery note for further information). Damage resulting from usual wear and tear, overloading, misuse and improper use and handling, respectively damage caused by the user or use contrary to the instruction manual, or damage that has been known to a buyer before purchasing the product, are excluded from the guarantee. Any complaints can only be accepted if the machine is complete, not dismantled, sent back to the manufacturer or authorised service centres (please see list of service centres). Keep the operating instructions, safety instructions and proof of purchase. Otherwise the manufacturer operates in accordance to its issued warranty conditions in latest update.